Tom,

It's RB-24E-25 FO 42-7423 reported to be named DRIP but no evidence seen. It was also used at Wendover AAF, UT, by 467th and 489th BGs during training. It was involved in a taxiing accident at Wendover on 12 Feb 44 while being used by 489th BG. See AAIR Accident Report database:

440212 RB-24E 42-7423844BS(H) 489BG(H) Wendover Field, Wendover, UT 2 TAC 0 Sherwood, Phillip B USA UT Wendover Field, Wendover, UT

Tom B.

